


## 3AB 500V CERAMIC FUSES

**ESKA**

Fast Acting (F) Part Number	Time Delay (T) Part Number	Ampere Rating
-	3ABDA.100/500V	100mA
-	3ABDA.125/500V	125mA
3AB.160/500V	3ABDA.160/500V	160mA
3AB.200/500V	3ABDA.200/500V	200mA
3AB.250/500V	3ABDA.250/500V	250mA
3AB.315/500V	3ABDA.315/500V	315mA
3AB.400/500V	3ABDA.400/500V	400mA
3AB.500/500V	3ABDA.500/500V	500mA
3AB.630/500V	3ABDA.630/500V	630mA
3AB.800/500V	3ABDA.800/500V	800mA
3AB001/500V	3ABDA001/500V	1A
3AB1.25/500V	3ABDA1.25/500V	1.25A
3AB01.6/500V	3ABDA01.6/500V	1.6A
3AB002/500V	3ABDA002/500V	2A
3AB02.5/500V	3ABDA02.5/500V	2.5A
3AB3.15/500V	3ABDA3.15/500V	3.15A
3AB004/500V	3ABDA004/500V	4A
3AB005/500V	3ABDA005/500V	5A
3AB06.3/500V	3ABDA06.3/500V	6.3A
3AB007/500V	-	7A
3AB008/500V	3ABDA008/500V	8A
3AB010/500V	3ABDA010/500V	10A
3AB12.5/500V	3ABDA12.5/500V	12.5A
3AB016/500V	3ABDA016/500V	16A
3AB020/500V	-	20A
3AB025/500V	-	25A



Dimensions in MM



Axial leaded versions also available.  
See page 149 for further information.

**I.R.:** 1000A

**Voltage:** As listed above

**Pack Size (bag):** 10, 100

**Holders:** Clips (p112-113), Inline (p122),  
Blocks (p146)


**Imperial Dimensions:** 1 1/4" x 1/4"

**Approvals:** RoHS

## 3AB 600V CERAMIC FUSES

**ESKA**

Fast Acting (F) Part Number	Ampere Rating
3AB.200/600V	200mA
3AB.500/600V	500mA
3AB.800/600V	800mA
3AB001/600V	1A
3AB002/600V	2A
3AB003/600V	3A
3AB005/600V	5A
3AB007/600V	7A
3AB010/600V	10A



Dimensions in MM



Axial leaded versions also available.  
See page 149 for further information.

**I.R.:** 1000A

**Voltage:** 600VAC

**Pack Size (bag):** 10, 100

**Holders:** Clips (p112-113),  
Blocks (p146)

**Imperial Dimensions:** 1 1/4" x 1/4"

**Approvals:** RoHS